

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/24/2018

Submitted Date:

12/24/2018

Document Number:

674902350**FIELD INSPECTION FORM**Loc ID 321567 Inspector Name: Beam, Russell On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 70430

Name of Operator: PINTAIL PETROLEUM LTD

Address: 225 N. MARKET #300

City: WICHITA State: KS Zip: 67202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Houseburg, Karen	316-263-2243 off/74165	khouseberg@pintailpetroleum.com	316-263-6479 fax
Kosola, Jason	(719) 641-0291	jason.kosola@state.co.us	
PHILLIPS, WALTER INNES		pintail@pintailpetroleum.com	(316) 263-2243

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207313	WELL	IJ	02/01/2017	DSPW	017-06248	CHAMPLIN 205 AMOCO A 1	IJ

**General Comment:**

Inspected Facilities									
Facility ID:	207313	Type:	WELL	API Number:	017-06248	Status:	IJ	Insp. Status:	IJ

--

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Potential spill was observed at the adjacent tank battery location. Operator has to make an assesment by the end of they week (12/28/2018) or earlier after coordination with Jason Kosola.

Corrective Action: Operator has to make an assesment by the end of they week (12/28/2018) or earlier after coordination with Jason Kosola.

Date: 12/28/2018

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401885540	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686636">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686636</a>
674902351	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686635</a>