

Final Reclamation and Stormwater Inspection

December 28, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 328437

Inspection Document #: 674902373

Weld County, CO

SWSW Section 28 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W28

Location ID: 328437



Photo 1. Photo taken from the well location, facing North. Appears the Operator has removed all well equipment from the P&A well.



Photo 2. Photo taken from the facility, facing North. See comments from Photo 1.