

**Caerus Piceance LLC**  
**Api # 05-077-08824**  
**Inspection # 675001644**



**Photo from entrance of location**

**Caerus Piceance LLC**  
**Api # 05-077-08824**  
**Inspection # 675001644**



**Location photo from entrance**

**Inspection # 675001644**

**Photo of tank battery at tank**

Caerus Piceance LLC  
Api # 05-077-08824  
Inspection # 675001644



Well head info

