

# Inspection Photos

Operator: Hilcorp Energy

API: 05-067-07403

Date: 12/19/2018



**Photo 1. View of the project area from the northeastern corner facing center.**





**Photo 2. View of the eastern project area from the northeastern project area facing southward.**





**Photo 3. View of the western project area from the northwestern corner facing southward.**





**Photo 4. View of musk thistle (*Carduus nutans*) rosettes within the project area.**