

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401890086  
Receive Date:  
01/02/2019

Report taken by:  
Candice (Nikki) Graber

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATON

Name of Operator: SRC ENERGY INC	Operator No: 10311	<b>Phone Numbers</b>
Address: 1675 BROADWAY SUITE 2600		Phone: (970) 4755220
City: DENVER State: CO Zip: 80202		Mobile: ( )
Contact Person: Dave Castro	Email: dcastro@srcenergy.com	

PROJECT, PURPOSE & SITE INFORMATION

**PROJECT INFORMATION**  
Remediation Project #: 9447 Initial Form 27 Document #: 200438706

**PURPOSE INFORMATION**

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input checked="" type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

**SITE INFORMATION** N Multiple Facilites ( in accordance with Rule 909.c. )

Facility Type: SPILL OR RELEASE	Facility ID: 443097	API #: _____	County Name: WELD
Facility Name: Stroh 35-2	Latitude: 40.363116	Longitude: -104.855932	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWNE	Sec: 35	Twp: 5N	Range: 67W Meridian: 6 Sensitive Area? Yes

**SITE CONDITIONS**

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Agricultural

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

**Other Potential Receptors within 1/4 mile**

Loveland and Greeley Canal 0.1 miles north, unnamed pond 0.2 miles south, and single-family house 0.1 miles east.

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input type="checkbox"/> Oil                       | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate                | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	Source Well Impact	Site delineation samples
Yes	SOILS	70' E-W by 80' N-S by 10'	Excavation soil samples

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On August 28, 2015, subsurface impact was encountered during removal of a produced water vault at the Stroh 35-2 tank battery. Excavation activities were conducted to remove impacted soils.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

During excavation activities, soil samples were collected to confirm compliance with applicable COGCC Table 910-1 standards. Confirmation soil samples collected at the final extent of the excavation indicated compliance with COGCC Table 910-1 standards. Please refer to the LTE Excavation and Site Delineation Report and Proposed Remediation Strategy, dated January 5, 2016, for further details.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Groundwater was encountered in the open excavation at approximately 6 feet below ground surface. Analytical results indicated the groundwater sample exceeded the COGCC Table 910-1 standard for benzene. Per COGCC approval (document #2526676), monitoring wells MW01-A2, SB17, and SB20 will be monitored quarterly with the goal of obtaining four consecutive quarters with analytical results indicating compliance under static conditions.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 25  
Number of soil samples exceeding 910-1 4  
Was the areal and vertical extent of soil contamination delineated? Yes  
Approximate areal extent (square feet) 5600

### NA / ND

-- Highest concentration of TPH (mg/kg) 3555  
NA Highest concentration of SAR           
BTEX > 910-1 No  
Vertical Extent > 910-1 (in feet) 8

### Groundwater

Number of groundwater samples collected 53  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) 6'  
Number of groundwater monitoring wells installed 11  
Number of groundwater samples exceeding 910-1 5

-- Highest concentration of Benzene (µg/l) 465  
-- Highest concentration of Toluene (µg/l) 2.5  
-- Highest concentration of Ethylbenzene (µg/l) 3.2  
-- Highest concentration of Xylene (µg/l) 2.1  
NA Highest concentration of Methane (mg/l)         

### Surface Water

0 Number of surface water samples collected  
         Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)          Volume of liquid waste (barrels)         

Is further site investigation required?

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The partially buried concrete produced water tank on site was removed, and impacted soil and groundwater near the source area was excavated transported to the Waste Management North Weld Landfill in Ault, Colorado, for final disposal.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Following source removal excavation, an infiltration gallery was installed in the open excavation prior to backfilling. Confirmation soil samples indicated compliance with applicable COGCC Table 910-1 standards at the final extent of the excavation. BOS 200 will be injected into the subsurface via the infiltration gallery and discrete injection points in accordance with EPA Rule Authorization (File #CO50000-11065), to remediate remaining petroleum hydrocarbon impact in groundwater.

## Soil Remediation Summary

### In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

### Ex Situ

Yes \_\_\_\_\_ Excavate and offsite disposal  
If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 2100  
Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

Yes \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
 \_\_\_\_\_ Chemical oxidation  
 \_\_\_\_\_ Air sparge / Soil vapor extraction  
 \_\_\_\_\_ Natural Attenuation  
 \_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Per COGCC approval (Document #2526676), three monitoring wells (one source well and two downgradient) will be monitored with the goal of obtaining four consecutive quarters with analytical results indicating compliance with applicable COGCC Table 910-1 standards under static conditions.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:**  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

**Report Type:**  Groundwater Monitoring  Land Treatment Progress Report  O&M Report  
 Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? No

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Not Applicable. Well remains in production.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

# IMPLEMENTATION SCHEDULE

## **PRIOR DATES**

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. \_\_\_\_\_

## **SITE INVESTIGATION DATES**

Date of Initial Actions described in Site Investigation Plan (start date). \_\_\_\_\_

Date of commencement of Site Investigation. 09/01/2015

Date of completion of Site Investigation. 09/26/2017

## **REMEDIAL ACTION DATES**

Date of commencement of Remediation. 12/29/2015

Date of completion of Remediation. 12/31/2016

## **SITE RECLAMATION DATES**

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

**OPERATOR COMMENT**

This SF27 is to request closure/NFA of this remediation project. 2017Q1 monitoring report was the last update on this project, submitted with SF27 document number 401293800 on 5/25/17. Since then, quarterly groundwater monitoring continued until 4 consecutive quarters of Table 910-1 compliance was achieved under static conditions with the 2017Q3 quarterly sampling event. The 2017Q2 and 2017Q3 quarterly monitoring reports are attached with this document.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Dave Castro

Title: Sr. Env. Specialist

Submit Date: 01/02/2019

Email: dcastro@srcenergy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Candice (Nikki) Graber

Date: 01/02/2019

Remediation Project Number: 9447

**COA Type****Description**

	Operator shall properly plug and abandon all monitoring and remediation wells within 90 days (April 2, 2019).
	Based on the information presented, it appears that no further action is necessary at this time and the COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required. In addition, the surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules.  For locations with active ongoing oil and gas operations, comply with Rule 1003 interim reclamation requirements.

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

401890086	FORM 27-SUPPLEMENTAL-SUBMITTED
401890103	MONITORING REPORT
401890105	MONITORING REPORT

Total Attach: 3 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)