

Final Reclamation and Stormwater Inspection

December 28, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 328767

Inspection Document #: 674902374

Weld County, CO

NWSE Section 20 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328767



Photo 1. Photo taken from the access road, facing Southwest. Appears the Operator has performed final reclamation activities. However, the majority of the site is barren or covered in weedy, annual vegetation which includes but not limited to kochia, with little perennial grass cover establishment.



Photo 2. Photo taken from the location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328767



Photo 3. Photo taken from the location, facing West. See comments from Photo 1.



Photo 4. Photo taken from the location, facing Northeast. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328767



Photo 5. Photo taken from the access road, facing Northeast. Photo depicts apparent rill erosion along access road.



Photo 6. Photo taken from the access road, facing Southwest. See comments from Photo 5.