

# Final Reclamation and Stormwater Inspection

December 28, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 328768

Inspection Document #: 674902375

Weld County, CO

NWSE Section 20 T3N R64W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328768



**Photo 1.** Photo taken from the facility and access road, facing Northwest. Appears the Operator has performed final reclamation activities. However, the majority of the site is barren or covered in weedy, annual vegetation which includes but not limited to kochia and cheatgrass, with little perennial grass cover establishment.



**Photo 2.** Photo taken from the access road and facility, facing West. See comments from Photo 1.

## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328768



**Photo 3.** Photo taken from the access road, facing Southwest. See comments from Photo 1.



**Photo 4.** Photo taken from the access road, facing Southwest. Photo depicts apparent start of rill erosion along access road.



## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328768



**Photo 5.** Photo taken from the location, facing West. See comments from Photo 1.



**Photo 6.** Photo taken from the location. See comments from Photo 1.