

Final Reclamation and Stormwater Inspection

December 28, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 328452

Inspection Document #: 674902373

Weld County, CO

SENE Section 20 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328452



Photo 1. Photo taken from the access road and facility, facing Northeast. Appears the Operator has performed final reclamation activities. However, the majority of the site is barren or covered in weedy, annual vegetation which includes but not limited to kochia, with little perennial grass cover establishment.



Photo 2. Photo taken from the access road and facility, facing Northeast. Photo depicts rill erosion along access road and facility location.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328452



Photo 3. Photo taken from the access road and facility, facing Southwest. See comments from Photo 2.



Photo 4. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 328452



Photo 5. Photo taken from the location, facing South. See comments from Photo 1.



Photo 6. Photo taken from the access road, facing East. Note the gravel and access road remain and have not been reclaimed.