

**Inspection Photo (s)**  
**Benzel 1-9**  
**API # 05-045-07408**  
**Inspection # 689302862**



**Location Photo #1**



**Location Photo #2, Holes in secondary containment liner.**

**Inspection Photo (s)**  
**Benzel 1-9**  
**API # 05-045-07408**  
**Inspection # 689302862**



**Location Photo #3, Holes in secondary containment liner.**



**Location Photo #4, Holes in secondary containment liner.**