

Inspection Photos

Loc#335399

Operator: Caerus

Inspection Number: 692400481

Inspection Date: 12/23/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry to Northeast.

December 23, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMR Loc#335399



Photo#2:

Vegetation in Interim Reclamation areas could not be assessed due to snow cover

December 23, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMR Loc#335399



Photo#3:

One Interim Rec site in bottom of bowl area & adjacent to Wells appears to have been recently installed.

December 23, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMR Loc#335399