

Inspection Photos

Operator: Samson Resources

API: 05-067-05621

Date: 12/19/2018



Photo 1. View of risers on active location. Not apparent whether all risers are associated with producing well or whether some are remaining from PA well.



Photo 2. View of more risers on active location. Not apparent whether all risers are associated with producing well or whether some are remaining from PA well.