

Inspection Photos
Location Name: MEAGHER 10-1H
Location ID: 05-103-11854
Inspection: 679702448



Photo 1. Location looking northwest.



Photo 2. Separators.

Inspection Photos
Location Name: MEAGHER 10-1H
Location ID: 05-103-11854
Inspection: 679702448



Photo 3. Tank battery.



Photo 4. Well head.

Inspection Photos
Location Name: MEAGHER 10-1H
Location ID: 05-103-11854
Inspection: 679702448



Photo 5. Assortment of trash stored on location mixed in with usable equipment.