

Inspection Photos

Loc#335867

Operator: Berry Petroleum

Inspection Number: 692400493

Inspection Date: 12/24/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from South end to Northeast.

December 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet Loc#335867



Photo#2:
View along Westside Fill Slope.

December 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet Loc#335867



Photo#3:
Jersey barriers are stored at West edge of Pad.

December 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Berry Pet Loc#335867