

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2019

Submitted Date:

01/03/2019

Document Number:

689702342**FIELD INSPECTION FORM**

Loc ID 335806	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 33 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280076	WELL	PR	02/01/2014	GW	045-11175	N. PARACHUTE EF08B P27 595	PR
421110	WELL	PR	05/23/2012	GW	045-20282	N. Parachute EF08D-34 P27595	PR
421111	WELL	PR	10/17/2012	GW	045-20283	N. Parachute EF14F-27 P27595	PR
421112	WELL	PR	10/15/2012	GW	045-20284	N. Parachute EF01E-34 P27595	PR
421113	WELL	PR	11/14/2012	GW	045-20285	N. Parachute EF16F-27 P27595	PR
421114	WELL	PR	01/08/2013	GW	045-20286	N. Parachute EF11F-27 P27595	PR
421115	WELL	PR	05/23/2012	GW	045-20287	N. Parachute EF08B-34 P27595	PR
421116	WELL	PR	06/17/2011	GW	045-20288	N. Parachute EF08A-34 P27595	PR
421117	WELL	PR	07/12/2013	GW	045-20289	N. Parachute EF01C-34 P27595	PR
421118	WELL	PR	07/12/2013	GW	045-20290	N. Parachute EF11D-27 P27595	PR
421119	WELL	PR	01/08/2013	GW	045-20291	N. Parachute EF14A-27 P27595	PR
421120	WELL	PR	01/08/2013	GW	045-20292	N. Parachute EF09F-27 P27 59	PR
421121	WELL	PR	02/14/2013	GW	045-20293	N. Parachute EF14B-27 P27595	PR
421122	WELL	PR	02/14/2013	GW	045-20294	N. Parachute EF16C-27 P27595	PR

421123	WELL	PR	12/14/2012	GW	045-20295	N. Parachute EF16D-27 P27595	PR
421124	WELL	PR	12/01/2012	GW	045-20296	N. Parachute EF16E-27 P27595	PR
421125	WELL	PR	06/16/2012	GW	045-20297	N. Parachute EF01F-34 P27595	PR
421126	WELL	PR	06/08/2013	GW	045-20298	N. Parachute EF01A-34 P27595	PR
421127	WELL	PR	08/01/2014	GW	045-20299	N. Parachute EF09E-27 P27595	PR
421128	WELL	PR	01/08/2013	GW	045-20300	N. Parachute EF16A-27 P27595	PR
421129	WELL	PR	05/28/2013	GW	045-20301	N. Parachute EF11E-27 P27595	PR
421145	WELL	PR	04/01/2014	GW	045-20315	N. Parachute EF08E-34 P27595	PR
421147	WELL	PR	10/17/2012	GW	045-20317	N. Parachute EF14E-27 P27595	PR
421148	WELL	PR	11/12/2012	GW	045-20318	N. Parachute EF08F-34 P27595	PR
421149	WELL	PR	02/14/2013	GW	045-20319	N. Parachute EF14D-27 P27595	PR
421150	WELL	PR	12/12/2012	GW	045-20320	N. Parachute EF16B-27 P27595	PR
421152	WELL	PR	07/12/2013	GW	045-20322	N. Parachute EF01B-34 P27595	PR
421153	WELL	PR	07/12/2013	GW	045-20323	N. Parachute EF09D-27 P27595	PR
421154	WELL	PR	10/15/2012	GW	045-20324	N. Parachute EF01D-34 P27595	PR

General Comment:

[Routine FIU General Field Inspection](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	No emergency services number or (911) on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/04/2019
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	800-791-7691		
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 9		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	280076	Type:	WELL	API Number:	045-11175	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421110	Type:	WELL	API Number:	045-20282	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421111	Type:	WELL	API Number:	045-20283	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421112	Type:	WELL	API Number:	045-20284	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421113	Type:	WELL	API Number:	045-20285	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421114	Type:	WELL	API Number:	045-20286	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421115	Type:	WELL	API Number:	045-20287	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421116	Type:	WELL	API Number:	045-20288	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	421117	Type:	WELL	API Number:	045-20289	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421118	Type:	WELL	API Number:	045-20290	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421119	Type:	WELL	API Number:	045-20291	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421120	Type:	WELL	API Number:	045-20292	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421121	Type:	WELL	API Number:	045-20293	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421122	Type:	WELL	API Number:	045-20294	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421123	Type:	WELL	API Number:	045-20295	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421124	Type:	WELL	API Number:	045-20296	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	421125	Type:	WELL	API Number:	045-20297	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421126	Type:	WELL	API Number:	045-20298	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421127	Type:	WELL	API Number:	045-20299	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421128	Type:	WELL	API Number:	045-20300	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421129	Type:	WELL	API Number:	045-20301	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421145	Type:	WELL	API Number:	045-20315	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421147	Type:	WELL	API Number:	045-20317	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421148	Type:	WELL	API Number:	045-20318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	421149	Type:	WELL	API Number:	045-20319	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421150	Type:	WELL	API Number:	045-20320	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421152	Type:	WELL	API Number:	045-20322	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421153	Type:	WELL	API Number:	045-20323	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421154	Type:	WELL	API Number:	045-20324	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Culverts				
Berms						
Check Dams						
Compaction						
				Material Handling And Spill Prevention		
		Ditches				
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702343	Inspection 689702342 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4694098