

Good morning ,

The inspection issues for KP are finished, here are some details.

#401877929—Two of the lines are dump lines that are still tested with the main line and two are for supply gas, they all have gauges on them now. Inspection plate has been replaced, all tanks are labeled, and yellow substance has been cleaned up.

#401877930—Riser is part of the water dump and now has a gauge for testing. The unused equipment on pad has been removed.

#401877931—Tanks have been labeled and unused equipment has been removed. The riser is a water line and is now locked and tagged.

Let me know if you have any questions.