

Final Reclamation Inspection

December 31, 2018

Operator: PDC ENERGY INC - #69175

API: 05-123-12572

Inspection Document #: 682404348

Weld County, CO

SWNE Section 18 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FRICK #32-18
API: 05-123-12572



Photo 1. Photo taken from the well location, facing West. No equipment observed at the well location. Photo illustrates subsidence at the PA well location with no vegetative growth.



Photo 2. Photo taken from the well location, facing East. Photo illustrates puncture vine throughout the entire access road which also appears to have spread off the access road.