

Inspection Photos

1/03/2019

Operator: RITCHIE EXPLORATION INC - 74770

Location ID: 387057

Inspection Doc. Number: 682504359

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the north end of the location, facing south. Photo shows areas of the location/well remains predominantly bare and exposed soil. Location does not meet reclamation requirements.



Photo 2: Photo taken from the south end of the location, facing north. Photo shows areas of the location/well remains predominantly bare and exposed soil. Location does not meet reclamation requirements.




Photo 3: Photo taken from the east end of the location, facing west. Photo shows erosion degradation due to stormwater runoff from the location. 6 foot measuring stock for reference.



Photo 4: Photo taken from the location. Photo shows location remains predominantly bare and exposed soil. 3x3 foot measuring stick for reference.



Photo 5: Photo taken from the adjacent reference area. Photo shows reference vegetation. Vegetation observed includes Blue grama, Buffalo grass, Wester wheat, Purple threeawn, sand dropseed, etc... 3x3 foot measuring stick for reference.



Photo 6: Photo taken from the north end of the location, facing east. Photo shows a section of access road/culvert that was constructed to cross a drainage. Access road requires reclamation including removal of culvert and restoration of the drainage.



Photo 7: Photo taken from the north end of the location, facing east. Photo shows a section of access road/culvert that was constructed to cross a drainage. Access road requires reclamation including removal of culvert and restoration of the drainage.



Photo 8: Photo taken from the access road, east of the location. Vegetation appears to have achieved uniform establishment on access road.