

# Final Reclamation Inspection

December 31, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-17647

Inspection Document #: 682404351

Weld County, CO

NWNE Section 18 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Photo taken from the well location, facing West. No equipment observed at the well location. Photo illustrates subsidence at the PA well location with no vegetative growth.

Inspection Photos  
Location Name: FRICK #C 18-2  
API: 05-123-17647



**Photo 2.** Photo taken from the northern well location access road, facing North. Photo illustrates no vegetative growth along the former access road.

Inspection Photos  
Location Name: FRICK #C 18-2  
API: 05-123-17647



**Photo 3.** Photo taken from the northern well location access road, facing South.  
See comments under Photo 2.