

Final Reclamation Inspection

December 31, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-28171

Inspection Document #: 682404357

Weld County, CO

NENE Section 13 T4N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HOW SAD C #18-31
API: 05-123-28171



Photo 1. Photo taken from the southern well and tank battery location, facing North. No equipment observed at the location. Photo illustrates little to no establishment of reference crops.

Inspection Photos
Location Name: HOW SAD C #18-31
API: 05-123-28171



Photo 2. Photo taken from the northwestern well and tank battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: HOW SAD C #18-31
API: 05-123-28171



Photo 3. Photo taken from the northwestern well and tank battery location, facing East. See comments under Photo 1.



Photo 4. Reference photo taken west of the well and tank battery location, facing West. Photo illustrates that disturbance areas are not reflective of reference area vegetative levels.