

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2019

Submitted Date:

01/04/2019

Document Number:

689500909**FIELD INSPECTION FORM**
 Loc ID 333191 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Candice (Nikki)		candice.graber@state.co.us	
Inspections, All		cogccinspection@pdce.com	
Longhurst, Mark		mark.longhurst@pdce.com	
Axelson, John		john.axelson@state.co.us	

General Comment:

COGCC inspection of produced water vault removal pursuant to the Matt #1 Administrative Order on Consent (AOC) order no. 1V-678 item #6. PDC notified COGCC of planned start date of 1/3/2019. Crew was in the process of removing square produced water vault at time of inspection. Possible soil impacts were observed on the north wall/northeast corner of excavation. Groundwater was not encountered at time of inspection.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment:

Suspected hydrocarbon impacted soil was observed on the north wall/northeast corner of excavation. COGCC spoke to Tasman personnel on site and required samples from all four excavation corners to be sent to laboratory for analysis.

Corrective Action:

Operator will provide confirmation soil sample analytical data that verifies compliance with Table 910-1, including laboratory analytical data from all four excavation corners. Include a soil sample location diagram and summary table of analytical results compared to table 910-1 standards when submitting the Form 27 Supplemental Site Investigation.

Date: 03/03/2019

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401893975	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4695040
689500910	Excavation photo 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4695035
689500911	Excavation photo 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4695036