

Inspection Photos
Location Name: MEAGHER 36-1
Location ID: 05-103-10768
Inspection: 679702457



Photo 1. Location looking northwest.




Photo 1. Container next to well head with illegible label.

Inspection Photos
Location Name: MEAGHER 36-1
Location ID: 05-103-10768
Inspection: 679702457




Photo 3. Well head.



Photo 4. Separator, gas meter building, tank battery.