

Inspection Photos

Location Name: WEAVER RIDGE 24-6

Location ID: 05-103-10522

Inspection: 679702463



Photo 1. Location looking north.



Photo 2. Gas meter, separator, well head.



Inspection Photos
Location Name: WEAVER RIDGE 24-6
Location ID: 05-103-10522
Inspection: 679702463



Photo 3. Well head.



Photo 4. Tank battery.

Inspection Photos

Location Name: WEAVER RIDGE 24-6

Location ID: 05-103-10522

Inspection: 679702463



Photo 5. Tank missing capacity volume of 300 bbl.