

## Inspection Photos

Location Name: WEAVER RIDGE 23-14

Location ID: 05-103-10668

Inspection: 679702472



**Photo 1. Location looking east.**



**Photo 2. Separators and gas meter buildings.**



**Inspection Photos**  
**Location Name: WEAVER RIDGE 23-14**  
**Location ID: 05-103-10668**  
**Inspection: 679702472**



**Photo 3. Tank battery.**



**Photo 4. Unmarked deadman.**