

Inspected Facilities

Facility ID: 241030 Type: WELL API Number: 123-08818 Status: PR Insp. Status: PR

COGCC Comments

Comment	User	Date
Followup inspection to inspection doc 691401008 in response to FIRR doc 401763131. Based on photos submitted by operator corrective actions have been completed. (photos attacked to FIRR)	beardsit	01/04/2019