

Inspection Photo (s)
Youberg SR 332-12
API # 05-045-23429
Inspection # 689302888



Location Photo #1



Location Photo #2

Inspection Photo (s)
Youberg SR 332-12
API # 05-045-23429
Inspection # 689302888



Location Photo #3



Location Photo #4, Label not posted on container.

Inspection Photo (s)
Youberg SR 332-12
API # 05-045-23429
Inspection # 689302888



Location Photo #5, Label not posted on container.



Location Photo #6, Inadequate berm around 80 BLL tank at wellhead.

Inspection Photo (s)
Youberg SR 332-12
API # 05-045-23429
Inspection # 689302888



**Location Photo #7, Inadequate berm around
80 BLL tank at wellhead.**