

# Final Reclamation Inspection

December 31, 2018

Operator: PDC ENERGY INC - #69175

API: 05-123-12782

Inspection Document #: 682404361

Weld County, CO

NENE Section 18 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MARY MILLS #41-18  
API: 05-123-12782



**Photo 1.** Photo taken from the eastern tank battery location, facing West. No equipment observed at the well location. Germination of desirable species was observed. Operator shall continue to monitor and manage the location until it meet Rule 1004 standards, including weed management.

Inspection Photos  
Location Name: MARY MILLS #41-18  
API: 05-123-12782



**Photo 2.** Close up photo taken from the tank battery location. Photo illustrates germination of desirable species.

Inspection Photos  
Location Name: MARY MILLS #41-18  
API: 05-123-12782



**Photo 3.** Photo taken from the northern well location access road, facing South. See comments under Photo 1. Note- There is an approved variance to leave the access point off CR 46 and retain the cattle guard.