

Final Reclamation and Stormwater Inspection

December 28, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP – 47120

Location ID: 328204

Inspection Document #: 674902379

Weld County, CO

NENE Section 20 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/3N64W20

Location ID: 328204



Photo 1. Photo taken from the access road, facing East. Appears the Operator has performed final reclamation activities. However, several portions of the site are barren or covered in weedy, annual vegetation which includes but not limited to cheatgrass, with little perennial grass cover establishment.



Photo 2. Photo taken from the location, facing Northeast. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/3N64W20

Location ID: 328204



Photo 3. Photo taken from the location. See comments from Photo 1.



Photo 4. Photo taken from the facility, facing West. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/3N64W20

Location ID: 328204



Photo 5. Photo taken from the reference location , facing North. Note the uniform perennial grass cover.



Photo 6. Photo taken from the reference location , facing East. See comments from Photo 5.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/3N64W20

Location ID: 328204



Photo 7. Photo taken from the reference location , facing South. See comments from Photo 5.



Photo 8. Photo taken from the reference location , facing West. See comments from Photo 5.