

Final Reclamation and Stormwater Inspection

December 28, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 328378

Inspection Document #: 674902380

Weld County, CO

NWSW Section 16 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W16

Location ID: 328378



Photo 1. Photo taken from the location, facing East. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, numerous areas of the site are barren or covered in weedy, annual vegetation which includes but not limited to cheatgrass, with little perennial grass cover establishment.



Photo 2. Photo taken from the location. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W16

Location ID: 328378



Photo 3. Photo taken from the location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W16

Location ID: 328378



Photo 5. Photo taken from the reference location , facing North. Note the uniform perennial grass cover.



Photo 6. Photo taken from the reference location , facing East. See comments from Photo 5.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W16

Location ID: 328378



Photo 7. Photo taken from the reference location , facing South. See comments from Photo 5.



Photo 8. Photo taken from the reference location , facing West. See comments from Photo 5.