

**Inspection Photos**  
**Location Name: Chris Wailes #1**  
**Location ID:319820**



**Photo 1 WH**



**Photo 2 TNK BTRY**

**Inspection Photos**  
**Location Name: Chris Wailes #1**  
**Location ID:319820**



**Photo 3 ECD plumbing installed**



**Photo 4 Meter run LOTO**



**Inspection Photos**  
**Location Name: Chris Wailes #1**  
**Location ID:319820**



**Photo 5 Stained soil around load VLV**



**Photo 6 Stained soil in seperator**