

# Final Reclamation and Stormwater Inspection

December 20, 2018

Operator: PETERSON ENERGY OPERATING INC – 68710

Location ID: 335761

Inspection Document #: 674902357

Weld County, CO

SWSE Section 34 T1N R67W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: PETERSON ENERGY OPERATING INC – 68710/1N67W34

Location ID: 335761



**Photo 1.** Photo taken from the location, facing West. Appears the Operator has performed final reclamation activities.



**Photo 2.** Photo taken from the location, facing East. This is on an Active Location.

## Inspection Photos

Location Name: PETERSON ENERGY OPERATING INC – 68710/1N67W34

Location ID: 335761



**Photo 3.** Photo taken from the location, facing South. Erosion control waddles left on site are deteriorating.



**Photo 4.** Photo taken from the location, facing South. See comments from Photo 3.