

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/07/2019

Submitted Date:

01/07/2019

Document Number:

692601048

FIELD INSPECTION FORM

Loc ID 303897 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253764	WELL	SI	09/01/2018	GW	125-07642	SCOFIELD 24-6	SI

General Comment:

Routine Inspection

Location

Lease Road:			
	Type	Access	
	comment:	Trail through farm ground	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Lease sign mounted to meter shed	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	OTHER	
	Comment:	Metal panels around meter shed	
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:	Metal panels around wellhead	
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
	Comment:	Telemetry equipment at meter shed	
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
	Comment:	Meter run in metal shed 540' south of wellhead	
Corrective Action:			Date:
Type: Vertical Separator	# 1		
	Comment:	Vertical gas separator in metal shed	
Corrective Action:			Date:

Venting:			
	Yes/No	NO	
	Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 253764 Type: WELL API Number: 125-07642 Status: SI Insp. Status: SI

Producing Well

Comment: [Producing. Casing production. Meter shed is 540' S of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT