

Inspection Photos

Location Name: WEAVER RIDGE 27-9

Location ID: 05-103-10579

Inspection: 679702488



Photo 1. Location looking northwest.



Photo2. Well 27-16 visible.



Inspection Photos

Location Name: WEAVER RIDGE 27-9

Location ID: 05-103-10579

Inspection: 679702488



Photo 3. Well 27-9 in foreground.



Photo 4. Emission control device.



Inspection Photos

Location Name: WEAVER RIDGE 27-9

Location ID: 05-103-10579

Inspection: 679702488



Photo 5. Tank volume capacity missing.



Photo 6. Deadman marker lying on ground.



Inspection Photos

Location Name: WEAVER RIDGE 27-9

Location ID: 05-103-10579

Inspection: 679702488



Photo 7. Unused equipment or trash next to 27-9 pump jack.



Photo 8. Unused building next to emission control device.



Inspection Photos

Location Name: WEAVER RIDGE 27-9

Location ID: 05-103-10579

Inspection: 679702488



Photo 9. Unused equipment near water tanks.



Photo 10. Unused barrel next well 27-16.