

Inspection Photos

Operator: BP America

API: 05-067-06972

Date: 12/21/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View the northern project area from the northwestern corner facing eastward.



Photo 3. View of the western project area from the northwestern project area facing southward.