

# Final Reclamation Inspection

January 2, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 318443

Inspection Document #: 682404375

Weld County, CO

SWNE Section 7 T1N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WOOLLEY A #1-7  
Location ID: 318443



**Photo 1.** Photo taken from the PA well location, facing South. Based on COGCC records, only 1 well was drilled and plugged at this location. All the other wells were abandoned.