

Interim Reclamation and Stormwater Inspection

January 2, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 335763

Inspection Document #: 682404379

Weld County, CO

NENW Section 30 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: VESSELS MINERALS A UNIT #2
Location ID: 335763



Photo 1. Photo taken from the eastern well location, facing North. Photo illustrates unmanaged Diffuse knapweed (*Centaurea diffusa*), a List B CO noxious weed. Operator shall properly remove the noxious weed.

Inspection Photos
Location Name: VESSELS MINERALS A UNIT #2
Location ID: 335763



Photo 2. Photo taken along a portion of well location access road, facing West. Photo illustrates unmanaged Scotch thistle (*Onopordum acanthium*), a List B CO noxious weed. Operator shall properly remove the noxious weed.

Inspection Photos
Location Name: VESSELS MINERALS A UNIT #2
Location ID: 335763



Photo 3. Photo taken along a portion of well location access road, facing West. See comments under Photo 2.