

Interim Reclamation Inspection

January 2, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-23791

Inspection Document #: 682404390

Arapahoe County, CO

SENE Section 7 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC




COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WOOLLEY #42-7
API: 05-123-23791



Google Earth aerial imagery taken 5/31/2018 illustrating the well location and unused tank battery (40.068886, -105.042389) which is ~900' northwest of the KPK location.



Photo 1. Photo taken from the southern location, facing West. Photo illustrates inadequate berms around tanks. Stormwater has eroded the berm and is eroding underneath one of the tanks- see next photo for a close up.

Inspection Photos
Location Name: WOOLLEY #42-7
API: 05-123-23791



Photo 2. Close up photo illustrating stormwater eroding underneath the tank.

Inspection Photos
Location Name: WOOLLEY #42-7
API: 05-123-23791



Photo 3. Close up photo taken of the previous tank illustrating a leak needing repair.