

Inspection Photos
Location Name: Dunning #1
Location ID: 307111



Crude oil tank berm on 11/27/18



Crude oil tank berm on 1/8/19

Inspection Photos
Location Name: Dunning #1
Location ID: 307111



Crude oil tank berm on 11/27/18

Crude oil tank berm on 1/8/19

Inspection Photos
Location Name: Dunning #1
Location ID: 307111



Wellhead on 11/27/18



Bradenhead valve on 1/8/19