

Inspection Photos  
Location Name: CORTINA 23-25  
Location ID: 334330



Colorado Oil & Gas Conservation Commission  
37.22957, -104.8399, 2299.0m, 85°  
2019/01/08 13:47:28



Colorado Oil & Gas Conservation Commission  
37.22925, -104.83987, 2291.0m, 80°  
2019/01/08 13:46:56

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN/METER HOUSE

**Inspection Photos**  
**Location Name: CORTINA 23-25**  
**Location ID: 334330**



**PHOTO 3: STAINED SOIL AROUND COMPRESSOR**

