

Inspection Photos

Location Name: B. Johnson-66N65W /11SWNW

Location #: 332038



Photo #1

B. Johnson 12-11 (05-123-21749) wellsite

Shut-In

Weeds

from prev. FIR



Photo #2

B. Johnson 12-11 wellsite

Shut-In

Weeds have been cleared



Inspection Photos

Location Name: B. Johnson-66N65W /11SWNW

Location #: 332038



Photo #3

B. Johnson 12-11 Battery

Shut-Down

from prev. FIR

