

Inspection Photo (s)
Rulison Federal 13A-17
API # 05-045-18761
Inspection # 689302918



Location Photo #1



Location Photo #2, Unused flow line on west end of tank battery.

Inspection Photo (s)
Rulison Federal 13A-17
API # 05-045-18761
Inspection # 689302918



**Location Photo #3, unused equipment near
entrance of location.**