

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2019

Submitted Date:

01/10/2019

Document Number:

688303402

FIELD INSPECTION FORM

Loc ID 458787 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26580
Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
Address: 925 N ELDRIDGE PARKWAY
City: HOUSTON State: TX Zip: 77079

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ConocoPhillips		COPColoradoReg@conocophillips.com	
Yu, Liang	281-467-5712	Liang.Yu@conocophillips.com	Regulatory Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458783	WELL	DG	01/06/2019		005-07387	Lussing Trust 4-64 19-20 3D1H	DG

General Comment:

Drilling and Surface Cementing Inspection
Multiwell pad

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	location sign at gate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	mud tanks and diesel storage tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Flare	# 1		corrective date
Comment:	emergency flare installed on NW corner of location		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 458783 Type: WELL API Number: 005-07387 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Nabors B16 Pusher/Rig Manager: Jason
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: commercial disposal

Comment: Surface TD 2165', float 2105.5', TD surface pipe 9 5/8", 36 weight, set at 2150.1'

Corrective Action: _____ Date: _____

Cement

Cement Contractor

Contractor Name: Halliburton Contractor Phone: _____

Surface Casing

Cement Volume (sx): 750 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: Class A, 12 ppg and 14.2 ppg, ~100 bbls back to surface
 1800 psi for 30 min casing test

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688303404	ConocoPhillips Lussing Trust 4-64 19-20 3D1H sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4700165
688303405	ConocoPhillips Lussing Trust 4-64 19-20 3D1H flare	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4700166