

Inspection Photos
Location Name: STATE-66N64W /16NWNE
Location #: 331504



Photo #1
State 16C (05-123-20801) wellsite
Shut-In
Overdue MIT
Weeds
from prev. FIR

Photo #2
State 16C wellsite
Shut-In
Current MIT
Weeds cleared

Inspection Photos

Location Name: STATE-66N64W /16NWNE

Location #: 331504



Photo #2

State 81 41-16, 16C Battery

Shut-Down

from prev. FIR

