

Inspection Photos
Location Name: Ivers Diggs 1-X
Location ID: 307099



Wellhead sign on 11/27/18



Wellhead sign on 1/10/19



Inspection Photos
Location Name: Ivers Diggs 1-X
Location ID: 307099



SW deadman on 11/27 18



SW deadman on 1/10/19

Inspection Photos
Location Name: Ivers Diggs 1-X
Location ID: 307099



NW deadman on 11/27/18



NW deadman on 1/10/19

Inspection Photos
Location Name: Ivers Diggs 1-X
Location ID: 307099



Crude oil tank berm on 11/27/18



Crude oil tank berm on 1/10/19

Inspection Photos
Location Name: Ivers Diggs 1-X
Location ID: 307099



Crude oil tank berm on 11/27/18



Crude oil tank berm on 1/10/19