

Inspection Photos
Location Name: Community #1
Location ID: 319888



Photo 1 Rig on WH



Photo 2 TNK BTRY

Inspection Photos
Location Name: Community #1
Location ID: 319888



Photo 3 RIG



Photo 4 Fluid around Pump

Inspection Photos
Location Name: Community #1
Location ID: 319888



Photo 5 Fluid by tank



Photo 6 Trash and fluid by WH

Inspection Photos
Location Name: Community #1
Location ID: 319888



Colorado Oil and Gas Conservation Commission
39.92683, -104.90074, 1544.7m
Jan 9, 2019 08:20:56



Colorado Oil and Gas Conservation Commission
39.92682, -104.90097, 1541.0m
Jan 9, 2019 11:03:37

Photo 7 Rig and BOP trailer

Photo 8 Wire line truck

Inspection Photos
Location Name: Community #1
Location ID: 319888



Photo 9 Cleaned up fluid and installed liner under tank



Photo 10 cleaned up fluid and trash