

Construction and Storm Water Inspection

January 8, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP – 47120

Location ID: 458702

Inspection Document #: 674902399

Weld County, CO

NENE Section 7 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N67W7

Location ID: 458702



Photo 1. Photo taken from the southwestern perimeter of the location, facing East. Photo illustrates the ditch and berm BMP that has been installed around the perimeter of the location.



Photo 2. Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N67W7

Location ID: 458702



Photo 3. Photo taken from the southeastern perimeter of the location, facing West. See comments from Photo 1.



Photo 4. Photo taken from the southeastern perimeter of the location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N67W7

Location ID: 458702



Photo 5. Photo taken from the northeastern perimeter of the location, facing West. See comments from Photo 1.



Photo 6. Photo taken from the northeastern perimeter of the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N67W7

Location ID: 458702



Photo 7. Photo taken from the northwestern perimeter of the location, facing East. See comments under Photo 1.



Photo 8. Photo taken from the northwestern perimeter of the location, facing South. See comments under Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N67W7

Location ID: 458702



Photo 9. Photo taken from the eastern perimeter of the location, facing East. Operator has installed a sediment trap with a temporarily stabilized outlet. The topsoil stockpile being stored along the eastern area has been temporarily stabilized with equipment tracking.



Photo 10. Photo taken from the eastern perimeter of the location, facing South. See comments from Photo 9.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N67W7

Location ID: 458702



Photo 11. Photo taken from the entrance of the location off CR 15, facing West. Operator has installed gravel potentially to limit tracking onto the county road. BMPs in proper functioning condition at the time of this inspection.