

Inspection Photos

1/10/2019

Operator: KLABZUBA OIL & GAS INC - 10148

Location ID: 393646

Inspection Doc. Number: 682504391

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from location, facing north. Photo shows vegetation over the reclamation area.



Photo 2: Photo taken from location, facing east. Photo shows vegetation over the reclamation area.



Photo 3: Photo taken from location, facing south. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: KLABZUBA OIL & GAS INC - 10148
Location ID: 393646



Photo 4: Photo taken from location, facing west. Photo shows vegetation over the reclamation area.



Photo 5: Photo taken from the northeast end of the tank battery facility (Southwest of well), facing southwest. Photo shows 3 above ground steel tanks remain on site.