

Inspection Photos

1/10/2019

Operator: KLABZUBA OIL & GAS INC - 10148

Location ID: 393701

Inspection Doc. Number: 682504395

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: KLABZUBA OIL & GAS INC - 10148
Location ID: 393701



Photo 1: Photo taken from the south end of the location, facing north. Previous inspection documented a concrete pump base remaining and that location remains predominantly bare and exposed soil. Base appears to have been removed, however location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted.



Photo 2: Photo taken from location. Photo shows location remains predominantly bare and exposed soil.



Photo 3: Photo taken from the east end of the location, facing west. Photo shows location remains predominantly bare and exposed soil, or dominated by undesirable weedy plant species.



Photo 4: Photo taken from the adjacent reference area. Vegetation observed over reference includes Sideoats grama, blue grama, switchgrass, western wheat, sand dropseed, etc...