

# Inspection Photos

1/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 313768

Inspection Doc. Number: 682504405

Morgan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the southwest corner of the location, facing northeast. Photo shows sign still remaining at location. Sign has not been removed or updated.



**Photo 2:** Photo taken from the southwest corner of the location. Photo shows sign still remaining at location. Photo shows sign and one of the four anchors that have not been removed from the location.



**Photo 3:** Photo taken from the west end of the well location, facing east. Photo shows large areas of the location remains predominantly bare and exposed soil desirable vegetative establishment is not uniform. Unable to find evidence that additional reclamation has been conducted.



**Photo 4:** Photo taken from south end of the well location, facing north. Photo shows large areas of the location remains predominantly bare and exposed soil desirable vegetative establishment is not uniform. Unable to find evidence that additional reclamation has been conducted.



**Photo 5:** Photo taken from the well location. Photo shows a valve (debris) and a riser that have been documented and required removal in previous inspections. Photo shows valve and riser have not been removed.



**Photo 6:** Photo taken from south end of the well location, facing north. Photo shows large areas of the location remains predominantly bare and exposed soil desirable vegetative establishment is not uniform. Unable to find evidence that additional reclamation has been conducted.



**Photo 7:** Photo taken from the well location. Photo shows gravel/road base remaining. Photo also shows large areas of the location remains predominantly bare and exposed soil desirable vegetative establishment is not uniform.



**Photo 8:** Photo taken from the adjacent reference area. Photo shows vegetation over reference. Vegetation observed predominantly Sand dropseed, blue grama, western wheatgrass, sand sage, etc...



**Photo 9:** Photo taken from the adjacent reference area. Photo shows vegetation over reference. See comments under photo 8.