

# Final Reclamation and Stormwater Inspection

January 8, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP – 47120

Location ID: 329327

Inspection Document #: 674902403

Weld County, CO

NWSE Section 15 T1N R66W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/1N66W15

Location ID: 329327



**Photo 1.** Photo taken from the access road, facing West. Appears the Operator has removed all equipment. Gravel remains throughout the location and access road which have not been re-contoured or re-graded



**Photo 2.** Photo taken from the location, facing South. See comments from Photo 1.

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/1N66W15

Location ID: 329327



**Photo 3.** Photo taken from the location, facing West. See comments from Photo 1.



**Photo 4.** Photo taken from the location, facing Northwest. See comments from Photo 1.

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/1N66W15

Location ID: 329327



**Photo 5.** Photo taken from the location. See comments from Photo 1.



**Photo 6.** Photo taken from the location. See comments from Photo 1.