

Final Reclamation and Stormwater Inspection

January 8, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 408851

Inspection Document #: 674902404

Weld County, CO

NESE Section 15 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC - 100322/1N66W15

Location ID: 408851



Photo 1. Photo taken from the access road, facing East. Appears the Operator has removed all equipment. Gravel remains throughout the location and access road which have not been re-contoured or re-graded

Photo 2. Photo taken from the access road, facing East. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC - 100322/1N66W15

Location ID: 408851



Photo 3. Photo taken from the location road, facing North. See comments from Photo 1.



Photo 4. Photo taken from the location road, facing West. See comments from Photo 1.